

# INSTRUCTIONS ON USE

Date

Scope and Activities:

**Miele**

Signature

## DESIGNATION OF HAZARDOUS SUBSTANCE

**ProCare Tex 11**

## RISKS TO HUMANS AND ENVIRONMENT



Causes severe eye irritation.

## PROTECTIVE MEASURES AND CODE OF CONDUCT



Wear safety goggles during work.

Avoid direct contact with skin and clothing.

Take off contaminated items of clothing immediately. In the event of skin contact, rinse liberally with water.



Avoid dust when refilling containers. Keep containers sealed tightly until used.

Apply skin protection lotion as protective measure.

## CONDUCT IN EVENT OF RISK

**Emergency call**



Measures in event of unintentional release of substances:

Clear and cordon off danger zone. Inform superior immediately.

Avoid any buildup of dust.


Risk of slipping in danger zone. Warn employees in area.

Dry disposal of product spillages (caution: dust buildup possible!). Transfer to clean container for re-use or disposal. Rinse off residuals with copious amounts of water.

In the event of a fire: Act in accordance with corporate fire safety regulations.

## FIRST AID

**Emergency call**



**Skin contact:** Remove contaminated clothing immediately; rinse affected skin liberally with water.

**Eye contact:** Rinse eyes under running water with eye-lids open for at least 10 minutes (protect unaffected eye, remove contact lenses). Consult a physician.

**Ingestion:** If person is conscious, immediately rinse mouth with water, drink large amounts of water. Do NOT induce vomiting, seek medical treatment.

**Inhalation:** Ensure ample fresh air, keep calm, half-upright position, loosen clothing. Assistance in event of breathing difficulties. If effects are severe, call doctor.

## APPROPRIATE DISPOSAL

**A**

Must be treated as hazardous waste in accordance with valid regulations.

This draft must be extended to include workplace-specific provisions and be signed by the employer.