

Sensor Sub-assembly

Sensor assembly

sensors with carbon brushes for detecting residual moisture in tumble dryers

EAN: 4002516803539 / Material number: 12575140 / Old Material Number:



- Type of fault: significant increase in noise due to worn carbon brushes
- Type of fault: laundry is still damp after drying cycle
- suitable for all T1
- including lid cap
- Repair time: approx. 30 minutes
- Tool: T20 screwdriver, protective gloves