

Sensor Sub-assembly

Sensor assembly

sensors with carbon brushes for detecting residual moisture in tumble dryers

EAN: 4002516869641 / Material number: 12575141 / Old Material Number:



- Type of fault: Significant increase in noise due to worn carbon brushes
- Type of fault: Laundry is still damp after drying cycle
- including lid cap
- Repair time: approx. 30 minutes
- Tool: T20 screwdriver, protective gloves