




















mm






T20



ø 2 mm



1.









1.16







2x









1x




2. 	2.1 	2.3 	2.4 	2.5 	
2.7 4x 	2.8 	2.10 	2.14 2x 	2.15 1x 	
2.16 2x 	2.17 2x 	2.18 1x 			
3. 	3.8 4x 	3.11 4x 	3.16 	3.18 	3.19 6x 




1.4**1.5****1.6****1.7****1.8****1.9**


1.10




1.11




1.12




1.13





1.14




1.15








1.16




2.






2.1





click !





2.2





2.3




2.4



2.5



2.6




2.7


4x






2.8




2.9




2.10




2.11




2.12




2.13




2.14




2.15




2.16




2.17




2.18




3.




3.1




3.2




3.3




3.4




3.5



3.6




3.7




3.8









4x




3.9




3.10







3.11




3.12




3.13




3.14



3.15




3.16




3.17

a




?




b





3.17a



?







3.18



3.19

6x



Miele & Cie. KG
Carl-Miele-Straße 29
33332 Gütersloh
Germany
Tel.: +49 5241 89-0
Internet: www.miele.com

